


September 2013 flooding at Strippgen, by Ed Holroyd

This image is of the April 2013 Flood Plain areas (blue on Google map of October 2012).



The white lines and numbers mark the approximate middles of photos taken at 9 AM 13 September 2013, after the flooding peak. The water did not cross the roadways except in one location in the middle. The water ran backwards through a culvert between photo locations 17 and 19. The cluster of photos 11-15 are of where the water ran over a pathway and large culvert. Two later photos show the water receding there.



11. Water also flooded part way to fence posts.



12. Debris caught in fence as creek exits Strippgen.



13. Van Bibber Creek in NE corner of Strippgen.



14. Overflow at culvert. Note brown in background.



15. at culvert



16. Creek at bend around willow tree.



17. Water flowing over roadway extension.



18. Flow marks across field.



19. Water flowing across field.



20. Flow splitting around large cottonwood tree.



21. Water coming off Open Space parking lot.



22. Parking lot water over roadway extension at best location for a gate to Open Space.



28. Receding water, 9:30 AM, 18 September 2013



84. Receding water, 7:50 AM, 29 September 2013, revealing some scouring above culvert.

I have refilled the scouring with rocks of various sizes.



Culvert, 16 August 2008 after a previous overflow.